

Update 300 Rover

Close AGPS package

Download Phoenix_300_v2.RTK.0024.zip save to desktop

Double click on the downloaded file

click on "Extract all files"

click next

click next

leave checkmark in box "Show extracted files"

click finish

In the window that opened showing the files extracted double click on the file that is the same as the com port your GPS receiver is connected to. This will open a black box that will show the progress of the update.

If the update does not start showing progress within 5 seconds turn the GPS receiver off and back on, the update should start showing progress.

When the update has completed successfully press any key to close black box.

Turn the GPS receiver off and back on.

Start the AGPS package that you use.

Press the menu button

Choose "Instrument Menu"

Choose "Control the Instrument"

Choose "Re-Initialize"

GPS unit should now be ready to use. It may take a few minutes for the Rover to reacquire a RTK fix.